

IN THE DRAWINGS:

Attached hereto are 4 replacement drawings sheets, replacing Figs. 5, 12, 13, and 14 as originally filed. Changes to the drawings are discussed in the Remarks section below.

BEST AVAILABLE COPY

Replacement Sheet

4/17

32 Bit Caller

64 Bit Caller




Fig. 5

JUL 7 3 1991
 105 MARK OBER

Replacement Sheet

12/17




Fig. 12




Fig. 13




Fig. 14